If you are using a printed copy of this procedure, and not the on-screen version, then you <u>MUST</u> make sure the dates at the bottom of the printed copy and the on-screen version match.

The on-screen version of the Collider-Accelerator Department Procedure is the Official Version.

Hard copies of all signed, official, C-A Operating Procedures are kept on file in the C-A ESHQ

Training Office, Bldg. 911A.

#### C-A OPERATIONS PROCEDURES MANUAL

#### 8.16.7 LINAC Compressed Air System

Text pages 2 through 3

# **Hand Processed Changes**

HPC No.	<u>Date</u>		Page Nos.		<u>Initials</u>	
		<del></del>				
	Approved:		Signature on 1	<u>File</u>		
		Collider-Accelerator Department Chairman			Date	

R. Grandinetti

#### 8.16.7 LINAC Compressed Air System

#### 1. Purpose

To provide operating instructions to the Water Systems Technicians for the operation of LINAC compressed air system.

#### 2. Responsibilities

Water Systems Technicians start and stop this system.

#### 3. <u>Prerequisites</u>

- 3.1 Startup Request permission from LINAC control.
- 3.2 Shutdown Request permission from LINAC control.
- 3.3 Qualified and trained Water Systems Technician.

#### 4. <u>Precautions</u>

- 4.1 Do not operate compressor with valves closed.
- 4.2 Do not operate compressor without cooling water on.

#### 5. Procedure

- 5.1 Verify that oil level is at least 1/2 full as indicated in the sight glass.
- 5.2 Open cooling water valves to compressor, oil cooler, and after cooler.
- 5.3 Open supply valves to system.
- 5.4 Inspect condition of compressor drive belts.
- 5.5 Turn on compressor circuit breaker.
- 5.6 Start compressor at local start-stop station.
- 5.7 Observe compressor cycling, general operation, and restore alarms.
- 5.8 Check oil temperature (< 180°F), oil level (1/2 full), discharge air pressure (< 125 psi).

- 5.9 Place compressed air dryer system control to on position and observe "on" indicator light.
- 5.10 For shutdown, turn off compressor and dryer. Close cooling water values to compressor, oil cooler and after cooler.

### 6. <u>Documentation</u>

None

# 7. References

LINAC flow diagram, C.T. Main Drawing #2484-402-M3.

# 8. Attachments

None